



SEPLUS BATTERYMONITOR FIRMWARE UPDATE

DONGGUAN SEPLUS TECHNOLOGY CO., LTD


1. Click 'firmware update' (please disconnect the battery pack before clicking)

2. Choose the corresponding port number

- baud rate 19200

- click 'Open'

Note: If an error reported when updating, please select update files, and click download to try again.




3. Click the 'folder' icon

- select the firmware update file (with .ehex)

- Click 'Download'

SEPLoS BATTERYMONITOR FIRMWARE UPDATING GUIDE



- wait until the processing bar reaching 100% - Click 'OK'

And the firmware updated successfully.

